Date:

Tuesday, 29/04/2008 3:10:16 PM

User:

Julie Lecocq

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

Estimate Number

: 38886 : 10804

P.O. Number

This Issue

Prsht Rev.

: 29/04/2008

: NC

First Issue **Previous Run** : //

: 00015

Type

S.O. No. :

: SMALL /MED FAB

Part Number

Drawing Name

: D26483 - R08-026

: D2648-3

Drawing Number Project Number

Drawing Revision

Material

Due Date : 06/05/2008

Qty:

10 Um:

Each

Checked & Approved By

Comment

Written By

-JUD844.29

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D26483

Wearpad



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

10.0000 Each(s)

Wearpad

Original B33992

QC5

INSPECT WORK TO QURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

3.0

2.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify with a the new Batch #, and restock.

Location:



4.0

QC21



18/05/pg L

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U 5/205-08

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES				
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cateo	gory:	NCR: Yes	No DQ	A:	Date:	
		MI - 1844					d:	Date: _	
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification		Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign Date	Secti	Section C	Chief Eng	QC Inspector
1	1					1			

NOTE: Date & initial all entries